

Bentley and Associates, LLC 6683 Poplar Springs Rd Loudon , TN 37774 865-986-2516 Donnie Bentley TN Lic# 183

Home Inspection



Happy Home Buyer 101 Happy Home Lane Your town, TN 3333 todays date

Bentley and Associates, LLC

Table of Contents

Definitions	2
General Information	2
Lots and Grounds	3
Exterior	4
Roof	7
Attic	8
Garage/ Carport	9
Electrical	11
Structure	12
Crawl Space	13
Basement	14
Air Conditioning	15
Heating System	16
Plumbing	17
Fireplace/ Wood Stove	19
Kitchen	19
Bathroom	22
Bedroom	26
Living Space	27
Laundry Room/Area	30
Infrared Scan	31
Summary	33

Bentley and Associates, LLC

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

General Information

Property Information

Property Address 101 Happy Home Lane City Your town State TN Zip 3333 Contact Name Realtor Phone

Client Information

Client Name Happy Home Buyer Client Address City State Zip Phone

Inspection Company

Inspector Name Donnie Bentley Company Name Bentley and Associates, LLC Address 6683 Poplar Springs Rd City Loudon State TN Zip 37774 Phone 865-986-2516 Fax E-Mail bentleyshomeinspection@gmail.com Amount Recieved/ Services

Conditions

Others Present Buyer Property Occupied Occupied Estimated Age age of home Entrance Faces Inspection Date Buyers contract date Start Time 8:50am End Time 12:10pm Electric On Yes Water On Yes Gas/ Oil On Yes Temperature 75 Weather Sunny Soil Conditions Damp Space Below Grade Basement, Crawl Space Building Type Single family Garage Attached Sewage Disposal City How Verified No verification Water Source City How Verified No verification

Bentley and Associates, LLC

Lots and Grounds

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

- 1. Acceptable Driveway: Concrete
- 2. Acceptable Walks: Concrete
- 3. Acceptable Porch: Concrete
- 4. Acceptable Patio: Concrete
- 5. Acceptable Grading: Minor slope
- 6. View of Grading
- 7. View View of Grade



8. Acceptable Exterior Surface Drain: Surface drain

Lots and Grounds (Continued)

- 9. Acceptable Swale: Adequate slope and depth for drainage
- 10. Acceptable Vegetation: Shrubs Recommend trimming shrubs



11. Marginal

Fences: Privacy - Damaged areas



12. FYI Maintaining drainage systems, grade, and landscaping around the structure is important to prevent water intrusion. Grading should slope away from the structure and vegetation should not touch the structure in order to prevent water and pest intrusion. Drainage systems should move water far enough away to ensure it cannot flow back to the structure.

Exterior	
NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Accents Exterior Surface -

1. Views of Exterior

Bentley and Associates, LLC

Exterior (Continued)

2. Acceptable



Main, Sides and rear Exterior Surface

3. Views of Exterior

4. Marginal





Exterior (Continued)

- 5. Not Present Trim: Wood, Aluminum and vinyl
- 6. Views of Exterior
- 7. Acceptable Fascia: Aluminum clad
- 8. Marginal Soffits: Vinyl Small section loose in rear



- 9. Acceptable Door Bell: Working properly
- 10. Acceptable Entry Door: Fiberglass clad
- 11. Acceptable Patio Door: Sliding
- 12. Acceptable Windows: Vinyl
- 13. Acceptable Exterior Lighting: Surface mount
- 14. Acceptable Exterior Electric Outlets: 110 VAC GFCI
- 15. Acceptable Hose Bibs: Rotary
- 16. Acceptable Gas Meter: Outside



17. FYI Recommend inspecting all caulking, stained and painted areas annually for deterioration and maintain as needed.

Bentley and Associates, LLC

Roof

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1. Views of Roof

Main Roof Surface -

- 2. Method of Inspection: Ground level with binoculars
- 3. Acceptable Material: Asphalt shingle
- 4. Type: Gable
- 5. Approximate Age: 4 Years
- 6. Acceptable Flashing: Aluminum
- 7. Acceptable Valleys: Asphalt shingle
- 8. Acceptable Electrical Mast: Underground utilities
- 9. Acceptable Plumbing Vents: Present
- 10. Acceptable Gutters: Aluminum
- 11. Defective Downspouts: Aluminum Rear left side downspout is turning water into opening above soffit recommend repair and have a contractor evaluate to see if there is water damage inside wall and repair downspout

Pulled loose in rear, Recommend repair





12. Acceptable Leader/ Extension: Plastic, Splash blocks

Bentley and Associates, LLC

Attic

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1. View of Attic



Main Attic

- 2. Method of Inspection: In the attic
- 3. Defective

Access Pull down - Recommend adding nails to hole provided in the metal bracket at top Cover loose, recommend repair



- 4. Acceptable Unable to Inspect: 10%
- 5. Acceptable Roof Framing: Rafter, 2x4 Truss
- 6. Acceptable Sheathing: OSB
- 7. Acceptable Ventilation: Adequate
- 8. Acceptable Insulation: Blown in, Batts
- 9. Acceptable Insulation Depth: 8"
- 10. Acceptable Wiring/ Lighting: 110 VAC
- 11. Acceptable Moisture Penetration: Dry at the time of the inspection
- 12. FYI Recommend a qualified individual inspect the attic periodically for water, pest and rodent intrusion.

Bentley and Associates, LLC

Garage/ Carport

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

Attached Garage -

1. View of Garage



- 2. Type of Structure: Attached Car Spaces: 2
- 3. Acceptable Garage Doors: Metal Dents present



4. Defective

Garage door trim Aluminum clad - Evidence of past water intrusion, Caulk added, Soft area on overhead piece of wood trim. Recommend evaluation and repair by a licensed contractor



Garage/ Carport (Continued)

Garage door trim (continued)



5. Acceptable 6. Acceptable

Door Operation: Mechanized Door Opener: Overhead Door



- 7. Acceptable Exterior Surface: Same as house
- 8. Acceptable Service Doors: Composition materials
- 9. Acceptable Electrical: 110 VAC GFCI
- 10. Acceptable Ceiling: Paint Nail Pops present
- 11. Acceptable Walls: Paint
- 12. Acceptable Floor/ Foundation: Poured concrete
- 13. Acceptable Smoke Detector: Present
- 14. FYI All moving parts of garage doors and openers should be periodically inspected for safety and integrity.

Electrical

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

- 1. Service Size Amps: 200 Volts: 110-240 VAC
- 2. Acceptable Service: Aluminum
- 3. Acceptable 120 VAC Branch Circuits: Copper
- 4. Acceptable 240 VAC Branch Circuits: Copper
- 5. Acceptable Smoke Detectors: Present Recommend installing batteries
- 6. Acceptable Conductor Type: Non-metallic sheathed cable
- 7. Acceptable Ground: Visible wire going into ground
- Outside Electric Panel -
- 8. Acceptable Manufacturer: Cutler-Hammer



- 9. Acceptable Panel Cover Present, Good Condition
- 10. Maximum Capacity: 200 Amps
- 11. Acceptable Main Breaker Size: 200 Amps
- 12. Acceptable Breakers: Copper
- 13. Is the panel bonded? Yes
- 14. FYI All electrical repairs and updates should be performed by a licensed electrician.

Bentley and Associates, LLC

Structure

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1. Acceptable Structure Type: Wood frame



2. Acceptable

Foundation: Block - Small cracks present



- 3. Acceptable Differential Movement: No movement or displacement noted
- 4. Acceptable Beams: Solid wood
- 5. Acceptable Bearing Walls: Frame
- 6. Acceptable Joists/ Trusses: 2x10
- 7. Acceptable Piers/ Posts: Block piers, Steel posts Additional support has been added by a qualified contractor
- 8. Acceptable Subfloor: OSB
- 9. Acceptable Floor/ Slab: Poured slab
- 10. Acceptable Stairs/ Handrails: Present
- 11. FYI Most hairline cracks in foundation walls, poured slabs and finished walls/ ceilings are normal settlement, but should be monitored for adverse changes.

Bentley and Associates, LLC

Crawl Space

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

Main Crawl Space -

1. View from inside Crawl Space





- 2. Method of Inspection: In the crawl space
- 3. Acceptable Access: Door
- 4. Acceptable Moisture Intrusion: No moisture present at time of inspection
- 5. Acceptable Moisture Location: No moisture present at time of inspection
- 6. Acceptable Moisture Barrier: No moisture barrier present
- 7. Acceptable Insulation: Fiberglass

Crawl Space (Continued)

- 8. Acceptable Vapor Barrier: Paper
- 9. Acceptable Ventilation: Vents
- 10. Acceptable Electrical: 110 VAC
- 11. Crawlspaces should be inspected periodically by a qualified Pest Control Company for termites, pests and rodents.

Basement

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

Unfinished area Basement -

1. Views of basement



- 2. Acceptable Ceiling: Exposed framing
- 3. Acceptable Walls: Block
- 4. Acceptable Floor: Concrete Cracks present
- 5. Acceptable Electrical: 110 VAC GFCI
- 6. Acceptable Basement Stairs/ Railings: Present
- 7. Acceptable Insulation: Fiberglass
- 8. Acceptable Moisture Intrusion: Dry at the time of the inspection
- 9. Acceptable Smoke Detector: Present

Bentley and Associates, LLC

Air Conditioning

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

Main AC System -

- 1. Acceptable A/ C System Operation: Functional To avoid possible compressor damage due to outside temperature below 60 degrees, the unit was not tested.
- 2. Marginal Condensate Removal: PVC There is evidence of past overflow in the drain pan inside the attic. There is no safety overflow switch present. Recommend installing a safety switch and having a HVAC contractor evaluate system





- 3. Acceptable Exterior Unit: Pad mounted
- 4. Manufacturer: Goodman



Air Conditioning (Continued)

- 5. Area Served: Whole building Approximate Age: 4 Years
- 6. Fuel Type: Electric Temperature Differential: na
- 7. Type: Central A/C Capacity: 3.5 Ton
- 8. Acceptable Visible Coil: Aluminum outside
- 9. Marginal Refrigerant Lines: Copper Missing insulation on refrigerant line, Recommend adding insulation to line



- 10. Acceptable Electrical Disconnect: Present
- 11. Acceptable Exposed Ductwork: Metal and flexible duct work
- 12. Acceptable Blower Fan/ Filters: Direct drive with disposable filter
- 13. Acceptable Thermostats: Individual
- 14. FYI For system longevity and efficiency, filters should be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a qualified HVAC technician.

Heating System

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of
	inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Attic Heating System -

- 1. Acceptable Heating System Operation: Adequate
- 2. Manufacturer: Carrier



3. Type: Forced air Capacity: Adequate for home

Heating System (Continued)

- 4. Area Served: Whole building Approximate Age: 10 Years
- 5. Fuel Type: Natural gas
- 6. Acceptable Heat Exchanger: 4 Burner
- 7. Unable to Inspect: 90%
- 8. Acceptable Thermostats: Individual
- 9. Acceptable Blower Fan/ Filter: Direct drive with disposable filter
- 10. Acceptable Distribution: Metal and flexible duct
- 11. Acceptable Flue Pipe: Double wall
- 12. FYI For system longevity and efficiency, filters be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a qualified HVAC technician.

Plumbing

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1. Acceptable Service Line: Copper



- 2. Acceptable Main Water Shutoff: Garage
- 3. Acceptable Water Lines: Copper
- 4. Acceptable Drain Pipes: PVC
- 5. Acceptable Vent Pipes: PVC
- 6. Defective Gas Service Lines: Cast iron, CSST Yellow Corrugated Stainless Steel Tubing (CSST) gas line present and does not appear bonded. Recommend a qualified licensed electrician evaluate and make any necessary repairs. For more information visit www.csstsafety.com

Plumbing (Continued)

Gas Service Lines: (continued)



Garage Water Heater -

- 7. Acceptable Water Heater Operation: Adequate Stains noted
- 8. Manufacturer: Bradford-White



- 9. Type: Natural gas Capacity: 50 Gal.
- 10. Approximate Age: 10 Years Area Served: Whole building
- 11. Acceptable Flue Pipe: Double wall
- 12. Acceptable TPRV and Drain Tube: Copper
- 13. FYI Because water can be turned off during real estate sales and transfers, it is recommended that all visible plumbing lines, fixtures and connections be inspected at final walk through, and again periodically for leaks. Follow manufacturers maintenance recommendations for all mechanical devices (water heaters, septic pumps, etc.)

Bentley and Associates, LLC

Fireplace/ Wood Stove

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

Bonus room Fireplace -

- 1. Acceptable Fireplace Construction: Prefab
- 2. Acceptable Operation Working Properly
- 3. Type: Gas log
- 4. Acceptable Fireplace Insert: Standard
- 5. Acceptable Smoke Chamber: Metal and glass
- 6. Acceptable Flue: Through wall vent



- 7. Acceptable Hearth: Adequate
- 8. FYI Fireplaces should be cleaned and inspected before initial use for safety, then annually or according to use by a qualified professional.

Kitchen		
NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection	
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	
0	, , , , , , , , , , , , , , , , , , , ,	

Kitchen and dining area Kitchen -----

Kitchen (Continued)

2. View of Kitchen



3. Acceptable Ceiling: Paint

4. Acceptable Walls: Paint

5. Marginal

Floor: Tile - Cracks/ loose grout between tiles



6. Acceptable 7. Defective

table Windows: Good condition

Electrical: 110 VAC GFCI - GFCI Outlet on counter is cracked, Recommend replacement



8. Acceptable

HVAC Source: Present

Kitchen (Continued)

9. Acceptable

Plumbing/ Fixtures: Adequate



10. Acceptable 11. Acceptable 12. Acceptable 13. Acceptable Sink: Good condition Disposal: In-Sinkerator Dishwasher: Maytag

Cooking Appliances: Whirlpool



14. Acceptable

Ventilator: Present

15. Marginal

Refrigerator: Whirlpool - Door water despencer not working



Kitchen (Continued)

16. Acceptable

Microwave: General Electric



17. Acceptable Counter Tops: Good condition

18. Acceptable Cabinets: Good condition

Bathroom

NOTE: All definiti	NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.		
Not Present	Item not present or not found.		
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.		
Marginal	Item is not fully functional and requires repair or servicing.		
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.		

1st floor hall, 1/2 Bath Bathroom -

1. View of Bathroom



- 2. Acceptable Ceiling: Paint
- 3. Acceptable Walls: Paint Water stains present behind toilet

Walls: (continued)



- 4. Marginal
- Floor: Tile Cracks/ loose grout between tiles 5. Acceptable Doors: Working Properly
- Electrical: 110 VAC GFCI 6. Acceptable
- 7. Acceptable Ventilation: Present
- 8. Acceptable Faucets/ Traps: Adequate
- Sink/Basin: Pedestal 9. Acceptable
- 10. Defective
- Toilets: Adequate The toilet is loose at the floor and may require replacement of the wax seal




Master Bathroom -

11. View of Bathroom



View of Bathroom (continued)



12. Acceptable	Ceiling: Paint
13. Acceptable	Walls: Paint
14. Acceptable	Floor: Vinyl floor covering
15. Acceptable	Doors: Working Properly
16. Acceptable	Windows: Good condition
17. Acceptable	Electrical: 110 VAC GFCI
18. Acceptable	HVAC Source: Present
19. Marginal	Ventilation: Present - Loud operation
20. Defective	Faucets/ Traps: Adequate - Traps leaking under both sinks



- 21. Acceptable
- 22. Acceptable Counter/ Cabinet: Adequate
- 23. Defective

Tub/ Surround: Plastic/ Fiberglass - Hole with improper repair, Recommend repairs be made by a professional





25. Defective Sho

ctive Shower/ Surround: Plastic/ fiberglass - Hole with improper repair, Recommend repairs be made by a professional

Faucet dripping, Recommend repair



Upstairs Bathroom – 26. View of Bathroom



- 27. Acceptable Ceiling: Paint
- 28. Acceptable Walls: Paint
- 29. Acceptable Floor: Vinyl floor covering
- 30. Acceptable Doors: Working Properly
- 31. Acceptable Electrical: 110 VAC GFCI
- 32. Acceptable HVAC Source: Present
- 33. Acceptable Ventilation: Present
- 34. Acceptable Faucets/ Traps: Adequate
- 35. Acceptable Sink/ Basin: Single bowl
- 36. Acceptable Counter/ Cabinet: Adequate
- 37. Defective
- Tub/ Surround: Plastic/ Fiberglass Diverter stuck on shower control



38. Acceptable Toilets: Adequate

Bedroom

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1st Floor Master Bedroom -

1. View of Bedroom



- 2. Acceptable Closet: Walk In
- 3. Acceptable Ceiling: Paint
- 4. Acceptable Walls: Paint
- 5. Acceptable Floor: Carpet
- 6. Acceptable Doors: Working Properly Visible repair
- 7. Acceptable Windows: Good condition
- 8. Acceptable Electrical: 110 VAC
- 9. Acceptable HVAC Source: Present
- 10. Acceptable Smoke Detector: Present
- Rear Bedroom -
- 11. View of Bedroom



12. Acceptable Closet: Walk In 13. Acceptable Ceiling: Paint

Bedroom (Continued)

- 14. Acceptable Walls: Paint
- 15. Acceptable Floor: Carpet
- 16. Acceptable Doors: Working Properly
- 17. Acceptable Windows: Good condition
- 18. Acceptable Electrical: 110 VAC Cover plate missing
- 19. Acceptable HVAC Source: Present
- 20. Acceptable Smoke Detector: Present

Center Bedroom -

21. View of Bedroom



- 22. Acceptable Closet: Single small
- 23. Acceptable Ceiling: Paint
- 24. Acceptable Walls: Paint
- 25. Acceptable Floor: Carpet
- 26. Acceptable Doors: Working Properly
- 27. Acceptable Windows: Good condition
- 28. Acceptable Electrical: 110 VAC
- 29. Acceptable HVAC Source: Present
- 30. Acceptable Smoke Detector: Present

Living Space

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of
	inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Living Room Living Space -

Living Space (Continued)

1. View of Living Area



- 2. Acceptable Ceiling: Paint 3. Acceptable
 - Walls: Paint
- 4. Marginal

Floor: Laminant - Loose trim



- 5. Acceptable Windows: Good condition
- Electrical: 110 VAC 6. Acceptable
- 7. Acceptable HVAC Source: Present
- 8. Acceptable Smoke Detector: Present
- Dining Room Living Space -
- 9. View of Living Area



- 10. Acceptable Ceiling: Paint
- Walls: Paint 11. Acceptable
- Floor: Tile 12. Acceptable

Living Space (Continued)

13. Marginal

Windows: Good condition - Right rear window not working properly



14. Acceptable E 15. Acceptable H Loft Living Space -

Electrical: 110 VAC HVAC Source: Present

16. View of Living Area



- 17. Acceptable Closet: Single small
- 18. Acceptable Ceiling: Paint
- 19. Acceptable Walls: Paint
- 20. Acceptable Floor: Carpet
- 21. Acceptable Windows: Good condition
- 22. Acceptable Electrical: 110 VAC
- 23. Acceptable HVAC Source: Present
- 24. Acceptable Smoke Detector: Present
- Bonus room Living Space -
- 25. View of Living Area



Living Space (Continued)

- 26. Acceptable Closet: Single small
- 27. Acceptable Ceiling: Paint
- 28. Acceptable Walls: Paint
- 29. Acceptable Floor: Carpet
- 30. Acceptable Doors: Working Properly
- 31. Acceptable Windows: Good condition
- 32. Acceptable Electrical: 110 VAC
- 33. Acceptable HVAC Source: Present
- 34. Acceptable Smoke Detector: Present

Laundry Room/ Area

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1 st Floor Laundry Room/Area -

1. View of Laundry room



- 2. Acceptable Ceiling: Paint
- 3. Acceptable Walls: Paint
- 4. Acceptable Floor: Tile
- 5. Marginal Doors: Bi-fold Doors need adjustment
- 6. Acceptable Electrical: 110 VAC
- 7. Acceptable HVAC Source: Present
- 8. Acceptable Washer Hose Bib: Ball valves
- 9. Acceptable Dryer Vent: Rigid metal
- 10. Acceptable Washer Drain: Wall mounted drain
- 11. Acceptable Washer and Dryer Electrical: 110 VAC, 220-240 VAC
- 12. FYI All washer hoses and connections should be inspected for leaks at final walk through and again periodically. Dryer lint traps, ducts and exit covers should also be occasionally inspected and cleaned to guard against lint accumulation that can be a fire hazard.

Bentley and Associates, LLC

Infrared Scan

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of	
	inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

1. Acceptable Building Scan No concerns were noted in scan - This is for your information and is not a complete energy scan of the building. This is some pictures we took during the inspection to provided a better home inspection. Infrared cameras can not see through walls but are very effective at documenting consistent temperature which is congruent with dry surfaces. If there were and concerns found they will be documented in the body of the report.



Final Comments

At Bentley and Associates, LLC., we strive to provide informative and thorough Home inspections, representing the condition of the property at the time of inspection. We recommend at final walk through, to observe areas that may have been previously blocked by personal items, furniture or area rugs. Visually inspect items you have asked to be repaired. We recommend that all repairs be done by a licensed or qualified professional in that field. Items or areas that we find in need of repair may have hidden damage that cannot be visually observed during the inspection, and thus may be found when repairs are being made. We do offer a re-inspection at a charge, should repairs be extensive or beyond your ability to properly access. If there are any concerns following this inspection or during final walk through, please contact us at 865-986-2516. Pictures always help and can be emailed to bentleyde@gmail.com. Thank you for using Bentley and Associates, LLC, for your Home Inspection.

Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

1. Fences: Privacy - Damaged areas



Exterior

2. Main, Sides and rear Exterior Surface Type: Vinyl siding - Small holes and cracks in rear, Sagging from heat in rear corner, Loose section at front porch



Exterior (Continued)

Type: (continued)



3. Soffits: Vinyl - Small section loose in rear



Air Conditioning

4. Main AC System Condensate Removal: PVC - There is evidence of past overflow in the drain pan inside the attic. There is no safety overflow switch present. Recommend installing a safety switch and having a HVAC contractor evaluate system



Air Conditioning (Continued)

Condensate Removal: (continued)



5. Main AC System Refrigerant Lines: Copper - Missing insulation on refrigerant line, Recommend adding insulation to line



Kitchen

6. Kitchen and dining area Kitchen Floor: Tile - Cracks/ loose grout between tiles



7. Kitchen and dining area Kitchen Refrigerator: Whirlpool - Door water despencer not working

Kitchen (Continued)

Refrigerator: (continued)



Bathroom

- 8. 1st floor hall, 1/2 Bath Bathroom Floor: Tile Cracks/ loose grout between tiles
- 9. Master Bathroom Ventilation: Present Loud operation

Living Space

10. Living Room Living Space Floor: Laminant - Loose trim



11. Dining Room Living Space Windows: Good condition - Right rear window not working properly



Laundry Room/Area

12. 1st Floor Laundry Room/ Area Doors: Bi-fold - Doors need adjustment

Defective Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Roof

1. Downspouts: Aluminum - Rear left side downspout is turning water into opening above soffit recommend repair and have a contractor evaluate to see if there is water damage inside wall and repair downspout Pulled loose in rear, Recommend repair



Attic

2. Main Attic Access Pull down - Recommend adding nails to hole provided in the metal bracket at top Cover loose, recommend repair



Garage/ Carport

3. Attached Garage Garage door trim Aluminum clad - Evidence of past water intrusion, Caulk added, Soft area on overhead piece of wood trim. Recommend evaluation and repair by a licensed contractor

Garage/ Carport (Continued)

Garage door trim (continued)





Plumbing

4. Gas Service Lines: Cast iron, CSST - Yellow Corrugated Stainless Steel Tubing (CSST) gas line present and does not appear bonded. Recommend a qualified licensed electrician evaluate and make any necessary repairs. For more information visit www.csstsafety.com



Defective Summary (Continued)

Kitchen

5. Kitchen and dining area Kitchen Electrical: 110 VAC GFCI - GFCI Outlet on counter is cracked, Recommend replacement



Bathroom

6. 1st floor hall, 1/2 Bath Bathroom Toilets: Adequate - The toilet is loose at the floor and may require replacement of the wax seal



7. Master Bathroom Faucets/ Traps: Adequate - Traps leaking under both sinks



Defective Summary (Continued)

8. Master Bathroom Tub/ Surround: Plastic/ Fiberglass - Hole with improper repair, Recommend repairs be made by a professional



9. Master Bathroom Shower/ Surround: Plastic/ fiberglass - Hole with improper repair, Recommend repairs be made by a professional

Faucet dripping, Recommend repair



10. Upstairs Bathroom Tub/ Surround: Plastic/ Fiberglass - Diverter stuck on shower control

