

Bentley and Associates, LLC 6683 Poplar Springs Rd Loudon,, TN 37774 865-986-2516 Donnie Bentley #183

# Home Inspection



123 Any Street Your Town, TN 33333

### Table of Contents

Definitions	3
General Information	3
Lots and Grounds	4
Exterior	7
Roof	8
Attic	10
Electrical	12
Smoke Alarm	13
Garage/Carport	14
Structure	15
Crawl Space	16
Basement	17
Air Conditioning	19
Heating System	22
Plumbing	23
Bathroom	24
Bedroom	27
Living Space	30
Kitchen	32
Fireplace/Wood Stove	33
Laundry Room/Area	34
Dock	35

09:09 July 04, 2024

#### **Bentley and Associates, LLC**

# Table of Contents (continued)

Final Comments	37
Infrared Scan	38
Summary	46

09:09 July 04, 2024

Definitions		
time of inspection Acceptable Not Present Not Inspected Marginal Defective	s listed below refer to the property or item listed as inspected on this report at the Functional with no obvious signs of defect. Item not present or not found. Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection. Item is not fully functional and requires repair or servicing. Item needs immediate repair or replacement. It is unable to perform its intended function.	
General Information		
	Property Information	
Property Address 123 Any Street City Your Town State TN Zip 33333 Client Name: Happy Home Owner Contact Name: Your Realtor		

**Client Information** 

Inspection Company

Inspector Name Donnie Bentley Company Name Bentley and Associates, LLC Address 6683 Poplar Springs Rd City Loudon, State TN Zip 37774 Phone (865)986-2516 Email donnie@bentleyhomeinspection.com

Conditions

Others Present Buyer Property Occupied Occupied Estimated Age 1935 Entrance Faces West Start Time 9am End Time 1pm Acceptable Electric On Yes Acceptable Water On Yes Acceptable Gas On Yes Temperature 80 Weather Cloudy Soil Conditions Dry Space Below Grade Crawl Space Building Type Single family Garage Attached

09:09 July 04, 2024

# **General Information (Continued)**

Water Source City How Verified No Verification Sewage Disposal City How Verified No Verification

### Lots and Grounds

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

#### 1. View Views of Grade



- 2. Acceptable
- 3. Acceptable

Grading: Minor slope Driveway: Gravel



4. Acceptable

Walks: Concrete

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 5 of 50

# Lots and Grounds (Continued)

- 5. Acceptable
- 6. Acceptable

Steps/Stoops: Stone Porch: Tile, Brick



7. Marginal

Patio: Paver - Settlement noted, Uneven pavers



8. Acceptable Deck/Back Porch: Concrete



9. Defective

Deck Rails and Steps Metal - Cracked concrete, Spalling brick, A qualified contractor is recommended to evaluate and estimate repairs



09:09 July 04, 2024


Happy Home Owner 123 Any Street Page 6 of 50

### Lots and Grounds (Continued)

Deck Rails and Steps (continued)



- 10. View of Grading
- 11. Acceptable





- 12. Acceptable
  - ble Swale: Adequate slope and depth for drainage
- 13. Acceptable Vegetation:
- 14. Marginal

Vegetation: Trees and shrubs Retaining Walls: Brick, Block, Stone - Loose cap stones



15. FYI Maintaining drainage systems, grade, and landscaping around the structure is important to prevent water intrusion. Grading should slope away from the structure and vegetation should not touch the structure in order to prevent water and pest intrusion. Drainage systems should move water far enough away to ensure it cannot flow back to the structure.

### Exterior

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Main, Sides and rear Exterior Surface

1. View Views of Exterior



2. Acceptable Type: Brick veneer Dormers Exterior Surface

3. View Views of Exterior




- 4. Acceptable
- Type: Composite siding
- 5. Acceptable Trim: Wood, Vinyl, Aluminum
- 6. Views of Exterior
- 7. Acceptable Fascia: Wood
- 8. Acceptable Soffits: Wood, Vinyl
- 9. Acceptable Door Bell: Working properly
- 10. Acceptable Entry Door: Working properly
- 11. Acceptable Deck Door: Working properly
- 12. Acceptable Windows: Crank out
- 13. Acceptable Exterior Electric Outlets: 110 VAC GFCI
- 14. Acceptable Exterior Lighting: Surface mount

Happy Home Owner 123 Any Street Page 8 of 50

# Exterior (Continued)

15. Acceptable



#### 16. Acceptable



17. FYI Recommend inspecting all caulking, stained and painted areas annually for deterioration and maintain as needed. All windows are inspected as access allows. Most windows will be opened and closed during the inspection, Particular attention is paid to windows, but there are times we can not access windows to inspect. We will note in the report any Moisture inside the layers of glass we can see but this can be limited by window treatments, rainy days, fog, or many other factors. Sometimes the rubber seals migrate and if we see these things we will write up in report, let us know if you see any windows during the inspection or during your final walk through.

#### Roof

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Main Roof Surface -

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 9 of 50

# Roof (Continued)

1. View Views of Roof




- 2. Method of Inspection: Ground level with binoculars
- 3. Acceptable Material: Asphalt shingle
- 4. Approximate Age: 10 Years
- 5. Acceptable Flashing: Metal
- 6. Marginal Valleys: Metal Debris on roof, Recommend cleaning



7. Acceptable
 8. Acceptable

Plumbing Vents: Present Gutters: Metal

9. Acceptable





10. Acceptable

Leader/Extension: Present

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 10 of 50

# Roof (Continued)

Center Chimney -

11. Acceptable

Chimney: Brick - Surface spalling, Repairs recommended



- 12. Acceptable Flue/Flue Cap: Concrete Not all of the chimney could be inspected due to the height of the roof
- 13. Acceptable Chimney Flashing: Metal
- 14. FYI Recommend having the roofing system inspected annually for unusual wear or damage. Gutter and drain systems should be cleaned and maintained as needed.

#### Attic

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

#### Main Attic -

1. View Views of Attic



09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 11 of 50

### Attic (Continued)

View (continued)



- 2. Method of Inspection: In the attic
- 3. Acceptable Access Scuttle hole
- 4. Acceptable Roof Framing: Rafter
- 5. Acceptable Sheathing: Plywood
- 6. Acceptable Ventilation: Adequate
- 7. Marginal Insulation: Batts No insulation present in small area near hall bathroom, Recommend adding insulation to the area



- 8. Acceptable Insulation Depth: 10
- 9. Acceptable Wiring/Lighting: 110 VAC
- 10. Acceptable Moisture Penetration: Dry at the time of the inspection
- 11. FYI Recommend a qualified individual inspect the attic periodically for water, pest and rodent intrusion.

### Electrical

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

A	Acceptable	Functional with no obvious signs of defect.
Ν	lot Present	Item not present or not found.
Ν	lot Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
		inaccessible, or disconnected at time of inspection.
Ν	/larginal	Item is not fully functional and requires repair or servicing.
Ľ	Defective	Item needs immediate repair or replacement. It is unable to perform its intended
		function.

- 1. Service Size Amps: 400 Volts: 110-240 VAC
- Electrical Mast: Underground utilities 2. Acceptable



- 3. Acceptable Service: Copper
- 4. Acceptable 120 VAC Branch Circuits: Copper
- 240 VAC Branch Circuits: Copper 5. Acceptable
- Conductor Type: Non-metallic sheathed cable 6. Acceptable
- Ground: Visible wire going into ground 7. Acceptable

Garage Electric Panel -

- 8. Acceptable Panel Cover Present, Good Condition Manufacturer: Square D
- 9. Acceptable



- 10. Maximum Capacity: 200 Amps
- Main Breaker Size: 200 Amps 11. Acceptable
- 12. Acceptable **Breakers: Copper**
- Panel Bonded Yes 13. Acceptable
- 14. FYI All electrical repairs and updates should be performed by a licensed electrician.

09:09 July 04, 2024

# Electrical (Continued)

Garage Electric Panel

15. Acceptable Panel Cover Present, Good Condition 16. Acceptable Manufacturer: Square D



- 17. Maximum Capacity: 200 Amps
- 18. Acceptable Main Breaker Size: 200 Amps
- 19. Acceptable Breakers: Copper
- 20. Acceptable Panel Bonded Yes
- 21. FYI All electrical repairs and updates should be performed by a licensed electrician.

#### Smoke Alarm

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

- 1. Acceptable Smoke Alarms: Smoke Detectors Present
- 2. Free Smoke Alarm including installation Information:

Enter your home address and contact your responding Fire Department, For information:

Click on Link Below or Copy and paste in your browser for a copy

- 3. https://tnmap.tn.gov/fdtn/
- 4. Home Fire Safety Sheet; Click on Link Below or Copy and paste in your browser for a copy
- 5. <u>https://www.tn.gov/content/dam/tn/commerce/documents/fire\_prevention/education-outreach/smokeal</u> <u>rmprogram/resources/HomeFireSafetyHandout2020.pdf</u>

09:09 July 04, 2024

### Garage/Carport

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

#### Attached Garage -

1. View Views of Garage





- 2. Type of Structure: Attached Car Spaces: 2
- 3. Acceptable Garage Doors: Metal
- 4. Acceptable Door Operation: Mechanized
- 5. Acceptable Door Opener: MarantecM
- 6. Acceptable Service Doors: Working properly
- 7. Acceptable Electrical: 110 VAC GFCI
- 8. Acceptable Ceiling: Good Condition Visible repairs



09:09 July 04, 2024

### Garage/Carport (Continued)

- 9. Acceptable Walls: Good Condition
- 10. Acceptable Windows: Good Condition
- 11. Acceptable Floor/Foundation: Poured concrete
- 12. Acceptable Smoke Alarm: Present
- 13. FYI All moving parts of garage doors and openers should be periodically inspected for safety and integrity.

#### Structure

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

-		
	Acceptable	Functional with no obvious signs of defect.
	Not Present	Item not present or not found.
	Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
		inaccessible, or disconnected at time of inspection.
	Marginal	Item is not fully functional and requires repair or servicing.
	Defective	Item needs immediate repair or replacement. It is unable to perform its intended
		function.

- 1. Acceptable Structure Type: Wood frame
- 2. Acceptable Foundation: Block, Brick
- 3. Acceptable Differential Movement: No movement or displacement noted
- 4. Acceptable Beams: Solid wood
- 5. Acceptable Bearing Walls: Frame
- 6. Marginal Bearing Walls for Basement addition: Frame Wood framing in contact with soil, Recommend pulling soil away from framing. Wood should not be in contact with soil



7. Acceptable Joists/Trusses: Wood floor joists

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 16 of 50

### Structure (Continued)

8. Acceptable

Piers/Posts: Steel posts



9. Defective

Added Piers/Posts: Wood posts - Additional wooden piers have been improperly installed, Wood in contact with soil, Not rated for the load they are supporting, A qualified contractor is recommended to evaluate and estimate repairs



- 10. Acceptable Subfloor: Dimensional wood
- 11. FYI Most hairline cracks in foundation walls, poured slabs and finished walls/ceilings are normal settlement, but should be monitored for adverse changes.

#### Crawl Space

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Main Crawl Space -

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 17 of 50

# Crawl Space (Continued)

1. View Views of Crawlspace







- 2. Method of Inspection: In the crawl space
- 3. Acceptable Access: Door
- 4. Acceptable Moisture Barrier: Plastic
- 5. Acceptable Insulation: Fiberglass
- 6. Acceptable Ventilation: Vents
- 7. Acceptable Moisture Intrusion: No moisture present at time of inspection
- 8. Acceptable Moisture Location: No moisture present at time of inspection
- 9. Crawlspaces should be inspected periodically by a qualified Pest Control Company for termites, pests and rodents.

#### Basement

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Partially finished area Basement -

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 18 of 50

### **Basement** (Continued)

1. View Views of Basement









- Ceiling: Good Condition
- 2. Acceptable 3. Acceptable Walls: Good Condition
- Floor: Good Condition 4. Acceptable
- 5. Marginal
- Doors: Working Properly Water damaged on door trim on exterior door



- 6. Acceptable
- 7. Acceptable
- 8. Acceptable

Electrical: 110 VAC Moisture Intrusion: Dry at the time of the inspection



09:09 July 04, 2024

### Air Conditioning

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

#### Outside AC System -

- 1. Marginal
- A/C System Operation: Functional at time of inspection The unit is nearing the end of the manufactures stated design life



- 2. Acceptable Condensate Removal: Present
- 3. Acceptable Exterior Unit: Pad mounted
- 4. Manufacturer: Trane
- 5. Area Served: Main Approximate Age: 20+ Years
- 6. Fuel Type: Electric Temperature Differential: 17
- 7. Type: Central A/C Capacity: 4 Ton
- 8. Acceptable Refrigerant Lines: Satisfactory condition
- 9. Acceptable Visible Coil: Good condition
- 10. Acceptable Thermostats: Individual
- 11. Acceptable Exposed Ductwork: Ductwork in good condition
- 12. Acceptable Blower Fan/Filters: Direct drive with disposable filter
- 13. Acceptable Electrical Disconnect: Present
- 14. FYI For system longevity and efficiency, filters should be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a qualified HVAC technician.

Outside AC System -

### Air Conditioning (Continued)

15. Acceptable

A/C System Operation: Functional at time of inspection



- 16. Acceptable Condensate Removal: Present
- 17. Acceptable Exterior Unit: Pad mounted
- 18. Manufacturer: Daikin
- 19. Area Served: Garage apartment Approximate Age: 3 years
- 20. Fuel Type: Electric Temperature Differential: Cooling properly
- 21. Type: Mini Split Capacity: 1 Ton
- 22. Acceptable Refrigerant Lines: Satisfactory condition
- 23. Acceptable Visible Coil: Good condition
- 24. Acceptable Thermostats: Individual
- 25. Acceptable Electrical Disconnect: Present
- 26. FYI For system longevity and efficiency, filters should be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a qualified HVAC technician.

Outside AC System -

27. Acceptable

A/C System Operation: Functional at time of inspection



- 28. Acceptable Condensate Removal: Present
- 29. Acceptable Exterior Unit: Pad mounted
- 30. Manufacturer: Gree
- 31. Area Served: Laundry Approximate Age: 7 Years
- 32. Fuel Type: Electric Temperature Differential: Cooling properly
- 33. Type: Mini Split Capacity: 1 Ton
- 34. Acceptable Refrigerant Lines: Satisfactory condition
- 35. Acceptable Visible Coil: Good condition

09:09 July 04, 2024

### Air Conditioning (Continued)

- Thermostats: Individual 36. Acceptable
- 37. Acceptable **Electrical Disconnect: Present**
- 38. FYI For system longevity and efficiency, filters should be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a qualified HVAC technician.
- Outside AC System -
- 39. Acceptable





- Condensate Removal: Present 40. Acceptable
- 41. Acceptable Exterior Unit: Pad mounted
- 42. Manufacturer: Mitsubishi
- 43. Area Served: Laundry and hall Approximate Age: 5 Years
- 44. Fuel Type: Electric Temperature Differential: Cooling properly
- 45. Type: Mini Split Capacity: 1 Ton
- Refrigerant Lines: Satisfactory condition 46. Acceptable
- 47. Acceptable Visible Coil: Good condition
- 48. Acceptable Thermostats: Individual
- 49. Acceptable **Electrical Disconnect: Present**
- 50. FYI For system longevity and efficiency, filters should be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a gualified HVAC technician.

09:09 July 04, 2024

### Heating System

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

#### Basement Heating System

1. Marginal Heating System Operation: Functional at time of inspection - Furnace existing beyond design life



- 2. Manufacturer: Trane
- 3. Type: Forced air Capacity: 100,000 BTUHR
- 4. Area Served: Main Approximate Age: 20 Years
- 5. Fuel Type: Natural gas
- 6. Acceptable Thermostats: Individual
- 7. Acceptable Blower Fan/Filter: Direct drive with disposable filter
- 8. Acceptable Distribution: Metal and flexible duct
- 9. Acceptable Heat Exchanger: Sealed unit
- 10. Acceptable Unable to Inspect 100%
- 11. Acceptable Gas Service Line/shutofff: Cast iron
- 12. Acceptable Flue Pipe: PVC
- 13. FYI For system longevity and efficiency, filters be changed every 30 days or according to manufacturers recommendations, and the system be inspected and serviced annually by a qualified HVAC technician.

#### Plumbing NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

me	e of inspection	
	Acceptable	Functional with no obvious signs of defect.
	Not Present	Item not present or not found.
	Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
		inaccessible, or disconnected at time of inspection.
	Marginal	Item is not fully functional and requires repair or servicing.
	Defective	Item needs immediate repair or replacement. It is unable to perform its intended
		function.

- 1. Acceptable Service Line: PEX
- 2. Acceptable Main Water Shutoff: Basement
- 3. Acceptable Water Lines: Copper
- 4. Acceptable Drain Pipes: Cast iron, PVC Cast iron drain pipes still present underground



5. Acceptable Vent Pipes: Cast iron

6. Acceptable Gas Service Lines: Cast iron

Outside Water Heater -

7. Acceptable

able Water Heater Operation: Adequate



- 8. Manufacturer: Rheem
- 9. Type: Instantaneous Capacity: Tankless
- 10. Approximate Age: 8 Years Area Served: Kitchen side of home
- 11. Acceptable Flue Pipe: PVC
- 12. Acceptable TPRV and Drain Tube: Present
- 13. FYI Because water can be turned off during real estate sales and transfers, it is recommended that all visible plumbing lines, fixtures and connections be inspected at

### Plumbing (Continued)

final walk through, and again periodically for leaks. Follow manufacturers maintenance recommendations for all mechanical devices (water heaters, septic pumps, etc.)

Crawl space Water Heater -

14. Acceptable Water Heater Operation: Adequate



- 15. Manufacturer: Unable to see information tag
- 16. Type: Instantaneous Capacity: Tankless
- 17. Approximate Age: 7 Years Area Served: Master bedroom side of home
- 18. Acceptable Flue Pipe: Double wall
- 19. Acceptable TPRV and Drain Tube: Present
- 20. FYI Because water can be turned off during real estate sales and transfers, it is recommended that all visible plumbing lines, fixtures and connections be inspected at final walk through, and again periodically for leaks. Follow manufacturers maintenance recommendations for all mechanical devices (water heaters, septic pumps, etc.)

#### Bathroom

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Above Garage Bonus Bathroom

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 25 of 50

### **Bathroom** (Continued)

1. View View of Room







- Ceiling: Good Condition 2. Acceptable
- 3. Acceptable Walls: Good Condition
- 4. Acceptable Floor: Good Condition
- Doors: Working properly 5. Acceptable
- Electrical: 110 VAC GFCI 6. Acceptable
- 7. Acceptable **HVAC Source: Present**
- 8. Acceptable Faucets/Traps: Adequate
- 9. Acceptable Ventilation: Present
- 10. Acceptable Sink/Basin: Single bowl
- 11. Acceptable **Toilets:** Adequate
- 12. Acceptable Shower/Surround: Tile
- 1st floor Hall, 1/2 Bath Bathroom -
- 13. View View of Room



- 14. Acceptable
- Ceiling: Good Condition Walls: Good Condition 15. Acceptable
- 16. Acceptable
- 17. Acceptable
- 18. Acceptable
- Doors: Working properly

Floor: Good Condition

- Windows: Working properly
- Electrical: 110 VAC GFCI 19. Acceptable
- 20. Acceptable **HVAC Source: Present**
- 21. Acceptable Faucets/Traps: Adequate
- 22. Acceptable Ventilation: Present
- 23. Acceptable Sink/Basin: Single bowl

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 26 of 50

# **Bathroom** (Continued)

Toilets: Adequate 24. Acceptable Master Bathroom -25. View View of Room



- 26. Acceptable
- Ceiling: Good Condition 27. Acceptable Walls: Good Condition
- 28. Acceptable Floor: Good Condition
- 29. Acceptable
- Doors: Working properly
- Windows: Working properly 30. Acceptable
- 31. Acceptable Electrical: 110 VAC GFCI
- 32. Acceptable **HVAC Source: Present**
- 33. Acceptable Faucets/Traps: Adequate
- Ventilation: Present 34. Acceptable
- Sink/Basin: Single bowl 35. Acceptable
- 36. Acceptable **Toilets:** Adequate
- 37. Acceptable
- Spa Tub/Surround: Plastic/Fiberglass Air jets only



38. Acceptable

Shower/Surround: Glass surround

### Bathroom (Continued)

Basement, 1/2 Bath Bathroom -39. View View of Room



- 40. Acceptable Ceiling: Good Condition
- 41. Acceptable Walls: Good Condition
- 42. Acceptable Floor: Good Condition
- 43. Acceptable Doors: Working properly
- 44. Acceptable Electrical: 110 VAC GFCI
- 45. Acceptable HVAC Source: Present
- 46. Acceptable Faucets/Traps: Adequate
- 47. Marginal Ventilation: No ventilation No ventilation present, Ventilation recommended to outside
- 48. Acceptable Sink/Basin: Single bowl
- 49. Acceptable Toilets: Adequate

#### **Bedroom**

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Above Garage Bonus Room Bedroom -

1. View View of Room

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 28 of 50

### Bedroom (Continued)

View (continued)







- 2. Acceptable Closet: Single small
- 3. Acceptable Ceiling: Good Condition
- 4. Acceptable Walls: Good Condition
- 5. Acceptable Floor: Good Condition
- 6. Acceptable Doors: Working properly
- 7. Acceptable Windows: Working properly
- 8. Acceptable Electrical: 110 VAC
- 9. Acceptable HVAC Source: Present
- 10. Acceptable Smoke Alarms: Present
- Master Bedroom -
- 11. View View of Room



- 12. Acceptable Closet: Walk In
- 13. Acceptable Ceiling: Good Condition
- 14. Acceptable Walls: Good Condition
- 15. Acceptable Floor: Good Condition
- 16. Acceptable Doors: Working properly
- 17. Acceptable Windows: Working properly
- 18. Acceptable Electrical: 110 VAC
- 19. Acceptable HVAC Source: Present
- 20. Acceptable Smoke Alarms: Present

Upstairs, Front Bedroom-

### **Bedroom** (Continued)

21. View View of Room



- 22. Acceptable Closet: Single small
- Ceiling: Good Condition 23. Acceptable
- 24. Acceptable Walls: Good Condition
- 25. Acceptable Floor: Good Condition
- 26. Acceptable Doors: Working properly
- 27. Acceptable Windows: Working properly
- 28. Acceptable Electrical: 110 VAC
- 29. Acceptable **HVAC Source: Present**
- 30. Acceptable Smoke Alarms: Present
- Upstairs, Rear Bedroom -
- 31. View View of Room



- 32. Acceptable Closet: Single small
- Ceiling: Good Condition 33. Acceptable
- 34. Acceptable Walls: Good Condition
- 35. Acceptable Floor: Good Condition
- 36. Acceptable
- Doors: Working properly 37. Acceptable Windows: Working properly
- Electrical: 110 VAC 38. Acceptable
- 39. Acceptable **HVAC Source: Present**
- 40. Acceptable Smoke Alarms: Present

09:09 July 04, 2024

### **Living Space**

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Den Living Space -

1. View View of Room



- 2. Acceptable
- Ceiling: Good condition 3. Acceptable Walls: Good Condition
  - Floor: Good condition
- 4. Acceptable 5. Acceptable
- Doors: Metal exterior No porch, Safety rails present



6. Acceptable

Electrical: 110 VAC 7. Acceptable **HVAC Source: Present** 

Dining Room Living Space -

8. View View of Room



09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 31 of 50

### Living Space (Continued)

- Ceiling: Good condition 9. Acceptable
- 10. Acceptable Walls: Good Condition
- 11. Acceptable Floor: Good condition
- 12. Acceptable Windows: Working properly
- 13. Acceptable Electrical: 110 VAC
- 14. Acceptable **HVAC Source: Present**
- Living Room Living Space -
- 15. View View of Room



- 16. Acceptable
- Ceiling: Good condition 17. Acceptable
- 18. Marginal

Walls: Good Condition Floor: Good condition - Cracked tiles in foyer



- 19. Acceptable
- Windows: Working properly 20. Acceptable Electrical: 110 VAC
- 21. Acceptable
- **HVAC Source: Present**

### **Kitchen**

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Kitchen and pantry Kitchen

2. View View of Room







3. Acceptable

Ceiling: Good Condition

- Walls: Good Condition 4. Acceptable
- 5. Marginal

Floor: Good Condition - Cracks/Missing grout between tiles



- 6. Acceptable
- Windows: Working properly 7. Acceptable HVAC Source: Present
- Plumbing/Fixtures: Adequate 8. Acceptable
- 9. Acceptable
  - Sink: Good condition

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 33 of 50

### Kitchen (Continued)

- 10. Acceptable
- 11. Acceptable

Electrical: 110 VAC GFCI **Dishwasher: Operational** 



- 12. Acceptable 13. Acceptable
- Cooking Appliances: Operational Refrigerator: Operational



- 14. Acceptable
- Ventilator: Present 15. Acceptable Counter Tops: Good condition
- Cabinets: Good condition 16. Acceptable

# Fireplace/Wood Stove

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

Living Room Fireplace

- 1. Type: Wood burning
- 2. Acceptable Fireplace Construction: Brick

# Fireplace/Wood Stove (Continued)

- 3. Acceptable
- Smoke Chamber: Brick



- 4. Marginal
- Flue: Metal Recommend cleaning and re-inspection before using



Acceptable
 Acceptable

e Damper: Metal e Hearth: Adequate

# Laundry Room/Area

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

1st Floor Laundry Room/Area

1. View View of Room



09:09 July 04, 2024

### \_aundry Room/Area (Continued)

- 2. Acceptable Ceiling: Good Condition
- 3. Acceptable Walls: Good Condition
- 4. Acceptable Floor: Good Condition
- 5. Acceptable Doors: Working properly
- 6. Acceptable Electrical: 110 VAC GFCI
- 7. Acceptable HVAC Source: Present
- 8. Acceptable Washer Hose Bib: Wall mounted valves Visual inspection only
- 9. Acceptable Dryer Vent: Good Condition
- 10. Not Inspected Washer Drain: Wall mounted drain Visual inspection only
- 11. Acceptable Washer and Dryer Electrical: 110 VAC, 220-240 VAC
- 12. FYI All washer hoses and connections should be inspected for leaks at final walk through and again periodically. Dryer lint traps, ducts and exit covers should also be occasionally inspected and cleaned to guard against lint accumulation that can be a fire hazard.

#### Dock

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

1. View Views of Dock



Lake Docks/Seawalls

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 36 of 50

# Dock (Continued)

2. Acceptable




3. Marginal

Dock: Treated wood - Weather deck boards noted on most of deck, Some deck boards needs replacement on walkway, A qualified contractor is recommended to evaluate and make necessary repairs



4. Acceptable







5. Defective

Dock Electric 110 VAC - Recommend installing GFCI protected outlets, Lights not working possible blown bulbs daylight sensor present may not be coming on because of sensor

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 37 of 50

## Dock (Continued)

Dock Electric (continued)



6. Marginal

Boat House Roof Asphalt shingle - Visible granular loss noted



### **Final Comments**

At Bentley and Associates, LLC., we strive to provide informative and thorough Home inspections, representing the condition of the property at the time of inspection. We recommend at final walk through, to observe areas that may have been previously blocked by personal items, furniture or area rugs. Visually inspect items you have asked to be repaired. We recommend that all repairs be done by a licensed or qualified professional in that field. Items or areas that we find in need of repair may have hidden damage that cannot be visually observed during the inspection, and thus may be found when repairs are being made. We do offer a re-inspection at a charge, should repairs be extensive or beyond your ability to properly access.

If there are any concerns following this inspection or during final walk through, please contact us at 865-986-2516. Pictures always help and can be emailed to office@bentleyhomeinspection.com. Thank you for using Bentley and Associates, LLC, for your Home Inspection.

09:09 July 04, 2024

### **Infrared Scan**

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power,
	inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended
	function.

1. Acceptable Building Scan No concerns were noted in scan - This is for your information and is not a complete energy scan of the building. This is some pictures we took during the inspection to provided a better home inspection. Infrared cameras can not see through walls but are very effective at documenting consistent temperature which is congruent with dry surfaces. If there were and concerns found they will be documented in the body of the report.




09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 39 of 50




09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 40 of 50




09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 41 of 50




09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 42 of 50




09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 43 of 50



09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 44 of 50



09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 45 of 50

# Infrared Scan (Continued)



Palm-Tech Inspector, Copyright © 1998-2024, Palm-Tech

09:09 July 04, 2024

## **Marginal Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

- Lots and Grounds
- 1. Patio: Paver Settlement noted, Uneven pavers



2. Retaining Walls: Brick, Block, Stone - Loose cap stones



#### Roof

3. Valleys: Metal - Debris on roof, Recommend cleaning



Attic

4. Main Attic Insulation: Batts - No insulation present in small area near hall bathroom, Recommend adding insulation to the area

09:09 July 04, 2024

Happy Home Owner 123 Any Street Page 47 of 50

Attic (Continued)

Insulation: (continued)



#### Structure

5. Bearing Walls for Basement addition: Frame - Wood framing in contact with soil, Recommend pulling soil away from framing. Wood should not be in contact with soil



#### **Basement**

6. Partially finished area Basement Doors: Working Properly - Water damaged on door trim on exterior door



#### Air Conditioning

7. Outside AC System A/C System Operation: Functional at time of inspection - The unit is nearing the end of the manufactures stated design life



Palm-Tech Inspector, Copyright © 1998-2024, Palm-Tech

# Marginal Summary (Continued)

Heating System

8. Basement Heating System Heating System Operation: Functional at time of inspection
Furnace existing beyond design life



Bathroom

9. Basement, 1/2 Bath Bathroom Ventilation: No ventilation - No ventilation present, Ventilation recommended to outside

Living Space

10. Living Room Living Space Floor: Good condition - Cracked tiles in foyer



**Kitchen** 

11. Kitchen and pantry Kitchen Floor: Good Condition - Cracks/Missing grout between tiles




#### Fireplace/Wood Stove

12. Living Room Fireplace Flue: Metal - Recommend cleaning and re-inspection before using

## Fireplace/Wood Stove (Continued)

Flue: (continued)



Dock

13. Lake Docks/Seawalls Dock: Treated wood - Weather deck boards noted on most of deck, Some deck boards needs replacement on walkway, A qualified contractor is recommended to evaluate and make necessary repairs



14. Lake Docks/Seawalls Boat House Roof Asphalt shingle - Visible granular loss noted



09:09 July 04, 2024

### **Defective Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

#### Lots and Grounds

1. Deck Rails and Steps Metal - Cracked concrete, Spalling brick, A qualified contractor is recommended to evaluate and estimate repairs



#### **Structure**

2. Added Piers/Posts: Wood posts - Additional wooden piers have been improperly installed, Wood in contact with soil, Not rated for the load they are supporting, A qualified contractor is recommended to evaluate and estimate repairs



#### Dock

3. Lake Docks/Seawalls Dock Electric 110 VAC - Recommend installing GFCI protected outlets, Lights not working possible blown bulbs daylight sensor present may not be coming on because of sensor

